



COPY	4
BOARD.	1/1761-2
G.W.	
E.A.	
W. RES.	

INDIAN AND NORTHERN AFFAIRS - CANADA  
N.W.T. REGION  
MAY 10 2001  
WATER RESOURCES DIVISION  
YELLOWKNIFE, NT  
BERIC EVANS - MANAGER GEOPHYSICS

## INDUSTRIAL WATER USE INSPECTION REPORT

(OIL AND GAS EXPLORATION, PRODUCTION, PROCESSING AND REFINING)

DATE:	FEBRUARY 27, 2001.	COMPANY REP:	BRIAN BUHR - VERITAS/ONSITE.
LICENSEE:	BURLINGTON RESOURCES LTD.	LICENCE NUMBER:	N7LI-1761.

### WATER SUPPLY:

Source:	MACKENZIE RIVER AND VARIOUS UNNAMED LAKES.	Quantity Used:	≈ 5m <sup>3</sup> /day	Meter Rdg:	BY TRUCKLOAD.
---------	--	----------------	------------------------	------------	---------------

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Intake Facilities	A	Storage Structures	A	Treatment Systems	N/I	Recycling	N/A
Flow Meas. Device	A	Conveyance Lines	N/A	Pumping Stations	A	Modifications	N/A

Comments: LICENSEE IS KEEPING RECORD OF LOCATIONS AND QUANTITIES USED PER LOCATION. EACH LOCATION IS GPSed. NO PROBLEMS NOTED WITH WATER SUPPLY.

### WASTE DISPOSAL:

Well Wastes:	Drilling Sump	N/A	Off-Site Removal	N/A	Downhole	N/A	Landspread	N/A
Sewage:	Sewage Treat.	N/A	Camp Sump		Natural Water Body		Wetlands Treat.	N/A
	Continuous		Inter. Discharge					
Solid Waste:	Open Dump		Landfill		INCINERATOR Burn & Bury	U	Sludge Disposal	N/A

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Discharge Quality	N/A	Conveyance Lines	N/A	Disch. Meas. Dev.	N/A	Freeboard	N/A
Decant Process	N/A	Sump Treatment	N/A	Dykes, Berms	N/A	Seepages	N/A
Sump Liners	N/A	Runoff Diversion	N/A	Erosion	N/A	Spills	NONE REPORTED.

Effluent Discharge Rate:	N/A.	SNP Samples Collected:	N/A.
--------------------------	------	------------------------	------

Comments: GARBAGE INCINERATOR WAS LEAVING A FALLOUT PLUME OVER CAMP. LICENSEE WAS USING INCINERATOR TOILETS. GREYWATER WAS BEING DEPOSITED IN ICE/SNOW BERMED AREAS THEN SCRAPED UP AND SPREAD OVERLAND WHEN CAMP MOVES LOCATION. NON-COMBUSTIBLE GARBAGE IS Hauled TO THE AND/OR INUVIK LANDFILL SITES.

### GENERAL CONDITIONS:

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable N/I - Not Inspected

Maintenance	A	Records & Reporting	U	Surveillance Network Program (SNP)	N/A
Geotechnical Inspection	N/A	Posting of Facilities	N/A	Contingency Plan	NOT RECEIVED. U
A & R Plan	N/A	Modifications	N/A	Fuel/Product Storage	A
Groundwater Discharge	N/A	Chemical Storage	N/A	Annual Report	DUE MARCH 31/01.

Comments: NO EVIDENCE OF SPILL EQUIPMENT NEAR FUEL STORAGE. THE LICENSEE'S CONTINGENCY PLAN WAS DUE JANUARY 1, 2001. THE LICENSEE APPEARS TO BE NEGLIGENT IN SUBMITTING THIS PLAN.

Violation(s) of Act and/or Licence: VIOLATIONS: 1. PART F, ITEM 1; CONTINGENCY PLAN NOT SUBMITTED FOR BOARD APPROVAL.

General Comments: THERE WERE APPROXIMATELY 48 PEOPLE AT CAMP AT TIME OF THIS INSPECTIONS.

THE LICENSEE REPRESENTATIVES WERE ASKED TO CORRECT IMMEDIATELY ANY APPARENT WATER LICENCE VIOLATIONS. THIS ACTIVITY IS A MOBILE SEISMIC SLEIGH CAMP.

Additional Comments Attached: Yes  No  X

Inspector's Signature:

Licensee Representative's Title:

Not Available.

Inspector's Title:

WATER RESOURCES OFFICER

Licensee Representative's Signature:

Not Available.

