



### MUNICIPAL WATER USE INSPECTION FORM

DATE: November 19, 1996 COMPANY REP.: Richard Ross / Elizabeth Kinnear  
LICENSEE: Hamlet of AKLAVIK LICENCE #: N364-0570

#### WATER SUPPLY

Source (s): Mackenzie River, Peel Channel Quantity Used (to date): UNKNOWN  
Owner/Operator: Owner = GNWT; Operator = GNWT (estimate or actual)

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Intake Facilities: A Storage Structure A Treatment Systems A Chem. Storage A  
Flow Meas. Device A Convey. Lines N/A Pumping Stations A

Comments: Note: In order to prevent cross contamination, the facility should be kept neat and tidy.

#### WASTE DISPOSAL

Sewage Sewage Treatment System (primary, secondary or tertiary) Primary  
Natural Water body  Continuous Discharge (land or water)   
Seasonal Discharge \_\_\_\_\_ Wetlands Treatment \_\_\_\_\_ Trench \_\_\_\_\_  
Solid Waste: Owner/Operator: Owner = GNWT Operator = Hamlet  
Landfill \_\_\_\_\_ Burn & Landfill  Other \_\_\_\_\_

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Disch. Quality A Decant Structure N/A Erosion N/A  
Disch. Meas. Dev. A Dyke Inspection N/A Seepages N/A  
Dams, Dykes A Freeboard N/A Spills N/A  
Construcion A O & M Plan A A & R Plan N/A  
Periods of Discharge: A Effluent Discharge Rate: \_\_\_\_\_

Comments: SNP station not posted. Please place a SNP sign at station SNP 570-3.  
Solid waste disposal site was partially fenced.

#### FUEL STORAGE

Owner: \_\_\_\_\_ Operator \_\_\_\_\_ Condition of Tanks \_\_\_\_\_  
Berms & Liners \_\_\_\_\_ Water within berm: N/A Evidence of Leaks: \_\_\_\_\_  
Drainage Pipes \_\_\_\_\_ Pump Station and Catchment Berm \_\_\_\_\_  
Pipeline Condition \_\_\_\_\_ Not Applicable: \_\_\_\_\_

#### SURVEILLANCE NETWORK PROGRAM

Samples Collected: (Hamlet) October 15, 1996 - sample mix up. No BODs and bacteri bottle taken.  
(DIAND) November 19, 1996

Signs Posted: SNP Only SNP 570-1, the others were not Warning Yes.

Record & Reporting Acceptable, except for the lack of information in the annual report. The annual report was explained to the Assistant S.A.O.

Geotechnical Inspection: \_\_\_\_\_

Non-Compliance of Act or Licence: Violations: 1. Part A, Item 9: SNP 570-3 and 570-4 were not posted.

Page 2 attached Yes \_\_\_\_\_ No X

A SENIOR ADMIN. OFFICER.  
Licensee Representatives Title  
E. Hinnig  
Licensee Representatives Signature

SCOTT GALLUPE / Allen Kogiak  
Inspectors Name  
[Signature]  
Inspectors Signature